Under Review Notification

URF 2020-513

Raised By: Steven Drouin

Date: 20.02.03 Product Name: Door Latch

		"Y" or "N" Required for Each Part Do not leave blank									
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	oduction	Quarantine Tooling (Jigs, Fixtures, etc.)		IPP Under Review (Enginer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")	Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
D350-589-041 ZV	IIN-D350-589 Rev. E	Υ	Υ	N	Υ	Υ	Υ	N	Υ	513	
D350-589-011	IIN-D350-589 Rev. E	Υ	Υ	N	Υ	Υ	Υ	N	Υ	513	
D2586	D2586 Rev. E	Υ	Υ	N	Υ	Υ	Υ	N	Υ	513	Update Drawing
D350-588-041	lin-D350-588 Rev.D	Υ	Υ	N	Υ	Υ	Υ	N	Υ	513	

Description of Issue:

D2586 needs to be updated to add supplier change, Supplier added a flange in the interior of part,

Customer will not be able to install part if update is not done

2-4-2020

HOLD

Product #: D350-589/588

206135 not sailed. 206526 200524

Distribution:

VP Operations

Director of Operations

Director Quality Assurance

QC Coordinator

Director of Engineering

Chief Engineer

Engineering Project Managers

Engineering Clerk

Customer Support Manager

Production Engineers
Production Planners

Purchasing Manager

Technical Support

Product Manager - Solutions Provider Supply Chain Director / Senior Buyer

Marketing Eugene